

Elevating Performance Through



Training

Calibration

Software & spare support



www.caltechcalibration.in

Metallurgical / Stereo zoom microscope

PREVENTIVE MAINTENANCE FOR NIKON, ZEISS, OLYMPUS, LEICA, KEYENCE MICROSCOPE -

- > Clean outer surface of Microscope (Dirt, Grease & Old Stickers).
- > Check & Clean Head Assembly, both Eye Piece & all Objective Lenses.
- Clean Mechanical Stage & Lubricate stage assembly moving parts.
- > Check Centre illuminator, Condenser Apertures & Field Diagrams.
- Check ON/OFF Switch & Brightness Adjustments.
- > Check Stage Proper Travel, Inspect Focus Block.
- > Alignment of Head Assembly & Clean all Lenses.
- > Check & replace Lubrication in all Mechanical moving Components.
- Calibration Certificate which is traceable to NABL.
- Software, spares support and training.

